

Continuous Radon Monitor

Model Number: 1028
Calibration Date: 09/18/2009
Monitor Time: 1/28/2010 13:13

Serial Number: 49979119
CF: 2.75

Sun Nuclear #1028 Monitor



Inspector Information

Phone Number:
License Number:

Customer Information

Habershal Dr.
Atlanta
Georgia-30318

Site & Condition


Year Built: New

Structure Type: Single Family
Monitor Location: Finished Basement

Test Summary

Start Time: 01/25/2010 22:52
End Time: 01/27/2010 22:52
Measurement Interval(hr): 1.0
Elapse Time: 2 Days 0 hrs

Overall Avg: 2.6 pCi/l
EPA Avg: 2.6 pCi/l



***** 01/25/2010 *****

Time	Counts pCi/l	Flags
23:52	2.9	

***** 01/26/2010 *****

Time	Counts pCi/l	Flags
00:52	1.8	
01:52	3.6	
02:52	2.9	
03:52	2.2	
04:52	2.9	
05:52	3.3	
06:52	4.7	
07:52	3.6	
08:52	5.8	
09:52	4.7	
10:52	2.9	
11:52	4.4	
12:52	3.6	
13:52	3.6	
14:52	2.5	
15:52	1.8	
16:52	2.2	
17:52	3.3	
18:52	2.9	
19:52	1.1	
20:52	1.1	
21:52	1.5	
22:52	2.2	
23:52	5.1	

***** 01/27/2010 *****

Time	Counts pCi/l	Flags
00:52	2.9	
01:52	2.5	
02:52	2.5	
03:52	2.2	
04:52	3.6	
05:52	2.5	
06:52	1.8	
07:52	1.5	
08:52	2.9	
09:52	0.7	
10:52	1.5	
11:52	2.5	
12:52	2.5	

***** 01/27/2010 *****

Time	Counts	Flags
	pCi/l	
13:52	1.8	
14:52	1.8	
15:52	1.5	
16:52	2.2	
17:52	2.5	
18:52	1.8	
19:52	1.1	
20:52	2.2	
21:52	3.6	
22:52	1.5	

Error Flags:

M Motion:

Inspector Signature _____

PC Software Version: 2.1.3.0

Embedded Software Version: 106